

Appropriate LPE Markings



- Optical density (OD) and wavelengths covered physically inscribed (can be on lens or frame...placement differs between manufacturers)
- In good condition (no cracks, holes or broken components)
- Has good visual light transmission (if not inscribed on the glasses, the value can be found on the eyewear spec sheet)