

RADIOACTIVE CONTAMINATION WITH NO INJURIES

- Evacuate the laboratory immediately. Close and lock the door and prevent anyone from entering. During normal working hours, contact the Radiation Safety Office at 203-785-3555 and provide details of the accident.
- During off hours, evacuate the laboratory, close and lock the door, call 911 from any Yale phone and provide details of the accident including your phone number. The Campus Police will contact Radiation Safety staff. Radiation Safety staff will then contact you and give instructions.
- If you have to leave the area to call the Radiation Safety Office or 911, cover or remove your shoes before leaving the area if you suspect contamination and do not touch anything unnecessarily.
- Hold your breath when possible until leaving the immediate area of possible high airborne concentrations.

Accidents Containing Radioactive Material and Infectious Agents

- Deactivate the biohazard and notify Environmental Health and Safety at 203-785-3555. During off hours, call 911 from any Yale phone.

Fires, Explosions, etc. Involving Radioactive Material

- Leave the area immediately and proceed to a safe area. Sound the nearest fire alarm.
- Call 911 from any Yale phone.
- Call the Radiation Safety Office at 203-785-3555.
- Do not leave your safe area without first being monitored for radioactive contamination.
- Prevent unauthorized personnel from entering the hazard area.